


Care instructions ART. 206622

				
DO NOT IRON	DO NOT BLEACH	HAND WASH	DO NOT DRY CLEAN	DO NOT TUMBLE DRY

- Do not use chlorine
- Do not tumble dry
- Wash at a maximum temperature of 50°C

PVC fabric care

High-pressure washer at moderate pressure (max 60–80 bar) and distance ≥ 30 cm

Do not use solvents, bleach, or abrasive cleaners — these can degrade the PVC coating and UV protection layer.